

**IN STOCK AND
READY TO SHIP!**


REPLACEMENT FOR THE LATEST DHC-6 OIL COOLER BRACKET AND WASHER

DESIGNED WITH YOU IN MIND

A PDA replacement for the latest post MOD 6/2297 oil cooler pylon from the OEM.

COST EFFECTIVE REPLACEMENT

Our oil cooler pylon replaces all MOD status oil cooler pylons in all series of Twin Otter and is a cost-effective alternative to repairing or replacing your original.



TRANSPORT CANADA PDA22-15

RMA Part Number	OEM Part Number	Description
RMA-C6L1042-1	C6L1042-1	BRACKET
RMA-C6L1042-1	C6L1021-3	BRACKET
RMA-C6L1042-1	C6L1021-1	BRACKET
RMA-C6L1042-31	C6L1042-31	WASHER

ROCKY
MOUNTAIN
AIRCRAFT



129 MACLAURIN DRIVE | CALGARY, ALBERTA, T3Z 3S4 | PHONE 403-288-3305 | TOLL FREE 1-800-661-1130
INFO@ROCKYMOUNTAINAIRCRAFT.CA | WWW.ROCKYMOUNTAINAIRCRAFT.CA