



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APPROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
REPAIR DESIGN APPROVALS						
C-RA19-031/D Issue 1 Feb 8, 2019	-	-	DHC-6-100, -110, -200, -210, -300, -310, -320, -400	Repair Hydraulic Fluid Reservoir PNs C6HF1057-1 / -3	None	None
C-RA18-028/D Issue 1 Mar 16, 2018	-	-	DHC-6-100, -110, -200, -210, -300, -310, -320	Window Frame Repair - Rivetted Assembly	None	None
C-RA16-049/D Issue 1 Apr 25, 2016	-	-	DHC-6-100, -110, -200, -210, -300, -310, -320, -400	Lug Repair, Cockpit Seat Pedestal, PN C3FF20-5	None	None
C-RA13-166/D Issue 1 Oct 25, 2013	-	-	DHC-6-100, -200, -300	Repair Horizontal Stabilizer Skin	None	None
C-RA08-055/D Issue 3 Feb 7, 2014	-	-	DHC-6-100, -200, -300	Repair of Bleed Air Ducts	None	None
C-RA07-396/D Issue 1 Dec 31, 2007	-	-	DHC-6-100, -200, -300	Repair of Elevator End Rib P/N C6TE1026-27 and C6TE1026-29	None	None
C-RA06-255/D Issue 1 Aug 11, 2006	-	-	DHC-6-100, -200, -300	Generator cooling duct assembly repair	None	None
C-RA06-254/D Issue 1 Aug 11, 2006	-	-	DHC-6-100, -200, -300	Control surface tip weld repair	None	None
C-RA04-386/D Issue 2 Mar 04, 2019	-	-	DHC-6-100, -110, -200, -210, -300, -310, -320	Replacement of aluminum power wires	None	None
C-RA03-418/D Issue 1 Dec 1, 2003	-	-	DHC-6-100, -200, -300	Repair of LH & RH Wing Flap Hinge Arm	None	None
C-RA03-080/D Issue 1 Jul 16, 2003	-	-	DHC-6-100, -200, -300	Jack Pad Repair	None	None
C-RA03-079/D Issue 1 Aug 29, 2003	-	-	DHC-6-100, -200, -300	Bracket Assembly Repair	None	None
C-RA03-078/D Issue 1 Aug 22, 2003	-	-	DHC-6-100, -200, -300	Fuel Tube Repair	None	None
C-RA02-607/D Issue 1 Jan 31, 2002	-	-	DHC-6-300 (C-GHBP / 380)	Over-sized Fasteners on Upper Main Frame Splice	None	None
C-RA01-644/D Issue 1 Aug 3, 2001	-	-	DHC-6-300 (N204SA / 402)	Over-sized Fasteners on Main Frame Splice	None	None
C-RA01-163 Issue 1 Nov 15, 2001	-	-	DHC-6-100, -200, -300	Trim Cable Pulley Bracket Repair	None	None
C-RA01-003/D Issue 1 Jan 18, 2001	-	-	Beechcraft Kingair 100 (C-GXVX / B-18)	Main Spar Repair at Left Wings F.S. 78.0	None	None
C-RA93-054/D Issue 1 Apr 14, 1993	-	-	BRITTEN NORMAN BN2A 26 (C-GZGO / 2017)	Fuselage Repair	None	None



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APPROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
C-RA92-018/D Issue 1 Jan 28, 1992	-	-	BEECH 60 (Duke) (C-FBQC)	Loran Antenna Support Repair	None	None
C-RA92-017/D Issue 2 May 1, 1992	-	-	DHC-6-300 (C-FMYV / 374)	Sta 111.0 Skin Joint Repair	None	None
W-RA97-139 Issue 2 Jan 21, 2000	-	-	DHC-6-100, -200, -300	Fore Flap Hinge Arm Repair	None	None
W-RA97-039/D Issue 1 May 16, 1997	-	-	DHC-6-300 (C-GQKZ / 532)	Wing Repair	None	None
W-RA95-034/D Issue 3 Mar 20, 1996	-	-	DHC-6-300 (C-FTJJ / 325)	Wing Assembly Repair	None	MMS946001 Rev - Sep 15, 1995
PARTS DESIGN APPROVALS						
PDA19-11 Issue 1 Feb 14, 2019	-	-	DHC- 6-1, -100, -110, -200, -210, -300, -310, -320, -400	Replacement Seat Pedestal	None	None
PDA18-18 Issue 2 14 JUN 2019	-	-	DHC- 6-100, -110, -200, -210, -300, -310, -320, -400	Replacement Fuel Tube Assemblies	None	None
PDA18-10 Issue 1 May 22, 2018	-	-	DHC- 6-100, -110, -200, -210, -300, -310, -320, -400	Fuel Cell Sump Plate Assemblies	None	None
PDA16-11 Issue 2 14 JUN 2019	-	-	DHC-6-100, -110, -200, -210, -300, -310, -320, -400	Replacement Cabin Floor Rails	None	None
PDA15-14 Issue 2 Apr 01, 2020	-	-	DHC-6-100, -110, -200, -210, -300, -310, -320	Replacement Engine and Lower Cowl Wiring, Cable Assemblies	None	None
PDA15-10 Issue 1 Jul 16, 2015	-	-	DHC- 6-100, -200, -300	Replacement De-icing Timer	None	None
PDA13-4 Issue 3 Aug 4, 2017	-	-	DHC-6-100, -110, -200, -210, -300, -310, -320, -400	Replacement, Air Conditioning, Heating and Cooling Ducts	None	None
PDA07-11 Issue 3 Oct 15, 2013	-	-	DHC-6-100, -200, -300, -400	D-Nose Door Assembly	None	None
PDA02-19 Issue 2 Mar 29 2019	-	-	DHC-6-100, -110, -200, -210, -300, -310, -320	RMA-C6FS2417-3, Upper Fuselage Skin Panel (Aft)	None	None
PDA02-3 Issue 2 Mar 29 2019	-	-	DHC-6-100, -110, -200, -210, -300, -310, -320	RMA-C6FS2416-1, Upper Fuselage Skin Panel (Forward)	None	None
SUPPLEMENTAL TYPE CERTIFICATE (SERIAL NO. SPECIFIC)						
C-LSA20-061/D Issue 1 AUG 10, 2020	-	-	DHC-6-300 (748, 839)	Installation, FS 262 - 332 Segmented Cabin Floor Rails	None	E125931 Rev - 03 AUG 2020
C-LSA19-054/D Issue 1 DEC 23, 2019	-	-	DHC-6-300 (748)	Installation, Science Equipment, Wing Mounted Science Platform	E122030 Rev C 05 DEC 2019	E125932 Rev - 03 Aug 2020
C-LSA18-118/D Issue 2 July 20, 2020	SA04311NY	-	DHC-6-300 (680)	Installation, 27" x 36" Fuselage Cut-out	None	E122031 Rev - 19 NOV 2019
						E122032 Rev - 19 NOV 2019
						E122130 Rev B Oct. 06 2020
						E122131 Rev A Oct. 05 2020



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APPROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
C-LSA18-024/D Issue 3 Oct 26, 2018	SA04312NY	-	DHC-6-300 (680)	Installation, Research Provisions	None	E121231 Rev - Feb 26, 2018
						E121331 Rev A Apr 6, 2018
						E121831 Rev - Apr 6, 2018
						E121930 Rev - Oct 24, 2018
						E121931 Rev - Aug 22, 2018
						E121932 Rev - Aug 22, 2018
E122230 Rev - Oct 24, 2018						
C-LSA17-109/D Issue 1 Sep 27, 2017	-	-	DHC-6-300 (687, 729, 783)	Installation, Fuselage Plug for Airstair Doors, Enlarged Cargo Door Aircraft	None	Viking Air Ltd Maintenance Documents
C-LSA16-124/D Issue 1 Nov 8, 2016	-	-	Textron Aviation A185F	Installation of Modified Aft Passenger Seat Frame	None	None
C-LSA16-029/D Issue 1 Mar 4, 2016	-	-	Beech B99 (C-FWIK / U-39)	De-activation, Janitrol Heater	None	E115931 Rev A Mar 2, 2016
C-LSA15-058/D Issue 2 Jul 18, 2018	-	-	DHC-6-300 (782)	LifePort PLUS Installation	FMS-1734-01 Rev 1 May 12, 2015	MMS-1734-01 Rev 1 May 12, 2015
C-LSA14-200/D Issue 1 Dec 12, 2014	-	-	DHC-6-300 (VP-FAZ / 748, VP-FBB / 783, VP-FBC / 787, VP-FBL / 839)	Installation of Zeiss NT2 Drift Sight	E110430 Rev - Nov 27, 2014	E110431 Rev - Nov 27, 2014
C-LSA14-053/D Issue 1 Mar 27, 2014	-	-	Hawker Beechcraft A100 (C-GVMI / B222)	Chelton AIU-2 Interface to S-Tec System 65 Autopilot	E109830 Rev - Mar 27, 2014	150-045055 Rev L Sep 6, 2011
C-LSA14-040/D Issue 1 Mar 26, 2014	-	-	Hawker Beechcraft A100 (C-GVMI / B222)	Installation of Mid-Continent Instruments MD302 Standby Attitude Module (SAM)	E110630 Rev - Mar 20, 2014	E110631 Rev - Feb 1, 2014
C-LSA13-165/D Issue 2 Jan 29, 2016	-	-	Bombardier CL-215-6B11 (C-FIGJ / 2084, C-FNJC / 2077, C-FOFI / 2081, C-GMFW / 2082, C-GMFX / 2083, C-GMFY / 2078, C-GMFZ / 2086, C-FDNL / 2091, C-FYWK / 2094)	Artes C406-N ELT with Programming Adapter Installation	None	E109531 Rev - Nov 1, 2013
C-LSA13-157/D Issue 1 Oct 15, 2013	-	-	DHC-6-300 (VP-FAZ / 748, VP-FBB / 783, VP-FBC / 787, VP-FBL / 839)	Installation, Lower Fuselage Cutouts between FS 347 and 362	None	PSM 1-6-3
						PSM 1-6-7
C-LSA13-149/D Issue 1 Oct 10, 2013	-	-	DHC-7-102, -103 (C-GCPY / 101, C-GFFL / 074, C-FWZV / 81, C-GCEV / 63, C-GUAT / 10)	Switch installation to enable the Start Pac Model 3328 Special Ground Power Unit (GPU) to provide external DC power	None	PSM 1-7-2
C-LSA13-147/D Issue 1 Nov 8, 2013	-	-	DHC-6-300 (VP-FAZ / 748, VP-FBB / 783, VP-FBC / 787, VP-FBL / 839)	Installation of Launch Tube in Existing Fuselage Cut-out	None	E109431 Rev A Nov 19, 2013



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
C-LSA13-078/D Issue 1 Jul 15, 2013	-	-	Hawker Beechcraft B200C (C-GDPB / BL44)	Deviations to STC SA01933LA-D to install Garmin GPS-400W	E108430 Rev - Jul 15, 2013	190-00356-65 Rev C Feb 28, 2013
C-LSA13-039/D Issue 1 Feb 20, 2013	-	-	DHC-6-300 (VP-FAZ / 748, VP-FBB / 783, VP-FBC / 787, VP-FBL / 839)	Electrical System Upgrade to 250 Amps	E107830 Rev - Feb 12, 2013	PSM 1-63-2
C-LSA12-203/D Issue 1 Nov 9, 2012	-	-	Hawker Beechcraft 200, B200 (C-FCGU / BB301, C-GNHM / BB188, C-GTUC / BB268, C-GBYN / BB1232)	Deviations to STC SA01340LA for Installation of Sandel ST3400 TAWS/RMI, Class B	E107330 Rev - Nov 9, 2012	E107331 Rev - Oct 26, 2012
C-LSA12-172/D Issue 1 Sep 28, 2012	-	-	DHC-6 300 (VP-FAZ / 748)	Installation of Aerosol Inlet Probe or Could Droplet Probes	E106030 Rev - Sep 28, 2012	E106031 Rev - May 1, 2012
C-LSA12-114/D Issue 2 Oct 22, 2012	-	-	DHC-7-102, -103 (C-GCPY / 101, C-GUAT / 10)	Avionics upgrade to include KLN-900, MFRD, MKVI EGPWS, and Standby Attitude Indicator	E106330 Rev - Sep 28, 2012	E106331 Rev - May 1, 2012
					E106425 Rev A Aug 30, 2012	E106426 Rev A Aug 29, 2012
					E106435 Rev A Aug 30, 2012	E106436 Rev A Aug 29, 2012
					E106445 Rev A Aug 30, 2012	E106446 Rev A Aug 29, 2012
C-LSA12-092/D Issue 1 Oct 17, 2012	-	-	Cessna 208, 208B (C-GATY / 20800305, C-FKAY / 208B0470, C-FSKS / 208B0722, C-GATH / 208B1244)	Installation of Appareo Vision 1000 System	None	E105631 Rev - Apr 27, 2012
C-LSA11-170/D Issue 1 Oct 28, 2011	-	-	Bombardier CL-215-1A10 (TC-TKH / 1104, TC-TKT / 1097)	Installation of Max-Viz EVS-1500 Enhanced Vision System with Two Displays	E104430 Rev - Oct 18, 2011	E104431 Rev - Jul 5, 2011
C-LSA11-144/D Issue 2 Apr 18, 2017	-	-	Hawker Beechcraft B200 (C-GWUY / BB77, C-GACA / BB1309)	Installation of Mid-Continent 4200-10 Standby Attitude Indicator with MD-420 Emergency Power Supply	E103430 Rev A Mar 15, 2017	E103431 Rev - Apr 19, 2011
C-LSA11-117/D Issue 1 May 24, 2011	-	-	DHC-6-300 (C-FTMU / 782, C-FTSU / 451, C-FTWU / 372)	Engine Chip Detector	E103330 Rev - May 24, 2011	E103331 Rev - Apr 8, 2011
C-LSA11-096/D Issue 1 Apr 18, 2011	-	-	DHC-6-100 (C-GSKB / 99)	MVP-50T Engine Display System	E101530 Rev - Feb 9, 2012	E101531 Rev - Oct 12, 2010
C-LSA11-069/D Issue 4 Mar 14, 2014	-	-	Bombardier CL-215-1A10, CL-215-6B11 (C-GMFW / 2082, C-GMFX / 2083, C-GMFY / 2078, C-GMFZ / 2086, C-GBOW / 1087, C-GMAK / 1107)	Installation of ISAT-100 with GPS/ Irdium antenna	E103230 Rev - Apr 18, 2011	E106131 Rev - Nov 14, 2013
					None	E102831 Rev A Feb 22, 2013



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APPROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
C-LSA11-010/D Issue 1 Feb 7, 2011	-	-	Hawker Beechcraft 200 (C-GQNJ / BB275)	Deviations to STC SA01933LA-D to include an alternate HSI, autopilot, and interface to DAC GDC-31	E102030 Rev - Feb 7, 2011	190-00357-65 Rev B Jul 30, 2009
C-LSA10-265/D Issue 1 Dec 18, 2010	-	-	Hawker Beechcraft 99, 99A (C-FKHD / U11, C-FVCE / U118)	Installation of Mid-Continent 4200-10 Standby Attitude Indicator with MD420 Emergency Power Supply	E102430 Rev - Dec 17, 2010	E102431 Rev - Nov 17, 2010
C-LSA10-264/D Issue 2 Sep 15, 2016	-	-	Hawker Beechcraft 200, B200 (C-FCGU / BB301, C-GXHF / BB1343, C-FAKN / BB216)	Installation of Mid-Continent 4300-411 Standby Attitude Indicator on Co-pilot's side	E102630 Rev - Dec 16, 2010	E102631 Rev - Dec 7, 2010
C-LSA10-262/D Issue 1 Dec 15, 2010	-	-	Hawker Beechcraft 99 (C-GASW / U39)	Installation of Mid-Continent MD4300-411 Standby Attitude Indicator	E102330 Rev - Dec 15, 2010	E102331 Rev - Nov 16, 2010
C-LSA10-251/D Issue 1 Dec 15, 2010	-	-	Hawker Beechcraft 200 (C-FKJI / BB105, C-GJLI / BB347, C-GQNJ / BB275)	Installation Of L-3 Communications Skywatch HP MODEL SKY899 (TCAS 1)	E101930 Rev - Dec 14, 2010	E101931 Rev - Oct 12, 2010
C-LSA10-250/D Issue 1 Dec 10, 2010	-	-	Aero Commander 500-S (C-GKEE / 3308)	Installation Of Avidyne EXP-5000 PFD	E101830 Rev - Dec 7, 2010	E101831 Rev - Oct 12, 2010
C-LSA10-213/D Issue 1 Oct 19, 2010	-	-	Hawker Beechcraft 200C (C-GCVS / BL13)	Deviations To STC To Install Garmin GPS-400W	E101730 Rev - Oct 19, 2010	190-00356-65 Rev C Feb 28, 2013
C-LSA10-192/D Issue 1 Sep 8, 2010	-	-	British Aerospace BAE 146-200 (C-GCUP / E2096)	Installation Of Dual Honeywell GNS-XLS FMS	146-3461-01-1012 Rev IR Sep 8, 2010	146-3461-01-0002 Rev IR May 10, 2010
C-LSA10-083/D Issue 1 May 25, 2010	-	-	Raytheon C90A (C-FHLL / LJ1111)	Installation of Universal Avionics CVR-30B	None	E100831 Rev - Apr 19, 2010
C-LSA10-066/D Issue 1 Apr 6, 2010	-	-	Beech C90 (C-GTWW / LJ657)	Installation of Sandel ST3400 TAWS/RMI, Class B	E100630 Rev - Apr 1, 2010	E100631 Rev - Mar 18, 2010
C-LSA10-065/D Issue 1 Apr 6, 2010	-	-	Beech C90 (C-GTWW / LJ657), Raytheon C90A (C-FHLL / LJ1111)	For S/N LJ-657: Deviations to STC SA01552CH-D for the installation of L-3 Communications Skywatch HP TCAS 1 System, Model SKY899/ For S/N LJ-1111: Upgrade existing SKY497 to SKY899	E100530 Rev - Apr 7, 2010	ES90-210999-200 Rev IR Nov 14, 2001
C-LSA10-061/D Issue 1 Apr 28, 2010	-	-	Bombardier CL215-1A10 (C-GMAF / 1044)	Relocation Of ADF-60B Antenna	None	218431 Rev - Sep 8, 2009
C-LSA09-260/D Issue 1 Nov 10, 2009	-	-	Bombardier CL215-1A10 (C-FTUV / 1020, C-FTXI / 1016, C-GMAF / 1044, C-GUMW / 1065)	Installation of: Dual Collins VIR-32 VHF NAV systems/ VHF-22A Comm systems/ ADF-60B ADF systems, Collins DME-42 DME system/ TDR-94 Transponder system, Dual NAT N301A-000 Audio system, NAT NTX-138 FM system, SKYTRAC ISAT-100 Satcom system, Pilot & Co-pilot Collins RMI-36 indicators, Artex C4-6N ELT	None	218431 Rev - Sep 8, 2009
C-LSA09-069/D Issue 1 Mar 23, 2009	-	-	Bombardier CL215-1A10 (C-FTUV / 1020, C-FTXI / 1016, C-GMAF / 1044, C-GUMW / 1065)	Sandel SN4500 EHSI Installation	217630 Rev - Mar 30, 2009	217631 Rev - Mar 4, 2009
C-LSA09-068/D Issue 2 June 28, 2018	-	-	Bombardier CL215-1A10 (1068, 1087, 1107, 1016, 1020, 1044, 1065)	Garmin GPS 400W With SHADIN ADC-2000 & Garmin GDL-69 Installation	217530 Rev A Apr 16, 2009	217531 Rev - Mar 4, 2009
C-LSA09-048/D Issue 4 Jan 9, 2018	-	-	Beech 1900D (UE128, UE58, UE334, UE5, UE8, UE268, UE332, UE333)	Toilet installation	None	None
C-LSA07-260/D Issue 1 Oct 10, 2007	-	-	DHC-6-300 (C-FOPJ / 243, C-FOPJ / 344, C-FOPG / 232)	Installation of a Sandel SA4550 Primary Attitude Display	210730 Rev - Oct 9, 2007	210731 Rev - Sep 18, 2007



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APPROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
C-LSA07-198/D Issue 1 Jun 27, 2007	-	-	DHC-6-200, -300	Installation Of An Avionics Shelf in Tail	None	None
C-LSA07-095/D Issue 1 Mar 30, 2007	-	-	DHC-6-300 (C-FMRU / 788)	Installation Of Flight Crew Supplemental Oxygen System	FMS-1177-03 Rev 1 Mar 16, 2007	MMS-1177-01 Rev 2 Oct 7, 2008
C-LSA07-029/D Issue 3 May 5, 2009	-	-	Bombardier CL215-1A10 (C-FTUV / 1020, C-FTXI / 1016, C-GMAF / 1044, C-GMAK / 1107, C-GUMW / 1065)	Installation of L-3 Sky Watch HP (TCAS I) system and a EVS Technology Max Viz EVS-1000 Enhanced Vision System	210830 Rev - Mar 26, 2007 210930 Rev B Jun 3, 2008	210831 Rev B Jun 3, 2008
C-LSA06-383/D Issue 2 Mar 16, 2007	-	-	DHC-6-300 (C-FBLY / 244)	Installation Of Supplemental Oxygen System	FMS-1177-02 Rev 1 Feb 21, 2007	MMS-1177-01 Rev 2 Oct 7, 2008
C-LSA05-360/D Issue 1 Nov 1, 2005	-	-	DHC-6-300 (N48RF / 740)	Nose Boom Installation	FMS386401 Rev IR Nov 1, 2005	MMS386401 Oct 1, 2005
C-LSA05-234/D Issue 1 Aug 25, 2005	-	-	DHC-6-300 (VP-FAZ / 748)	Masin Installation	FMS370201 Rev 1 Aug 5, 2005	MMS370201 Rev 1 Apr 8, 2005
C-LSA05-200/D Issue 1 Nov 23, 2005	-	-	DHC-6-300 (C-FWAH)	IHAS 8000 Integrated Hazard Awareness System Installation	199230 Rev - Nov 22, 2005	199231 Rev - Oct 5, 2005
C-LSA05-132/D Issue 5 Nov 3, 2016	-	-	DHC-6-100, -200 (C-FASQ / 78, N97DZ / 97, C-FPOK / 116, N206EH / 194, N901ST / 208)	Hartzell HC-B3TN-3D(Y) Propeller Installation	FMS379501 Rev 4 Oct 21, 2016	MMS379501 Rev 4 Sep 26, 2016
C-LSA04-357/D Issue 1 Oct 20, 2004	-	-	Raytheon (Beech A100 (C-GZUZ / B-143)	Installation of a L-3 Communications - Aviation Recorders (FAIRCHILD) A100S Cockpit Voice Recorder System	None	195431 Rev - Oct 19, 2004
C-LSA04-177/D Issue 1 Jul 27, 2004	-	-	Raytheon 99A (C-FVCE / U118)	Installation of Single Garmin GNS-430 GPS/NAV/COMM System	194530 Rev - Jun 30, 2004	194131 Rev - Jul 1, 2004
C-LSA03-271/D Issue 1 Jul 16, 2003	-	-	DHC-6-300 (VP-FAZ / 748)	Electrical Conduit Installation	None	None
C-LSA03-137/D Issue 1 Dec 31, 2003	-	-	DHC-6-300 (C-FTXQ / 308)	Single GNS 430 GPS / NAV / COMM System Installation	94839-801 Rev - Oct 20, 2003	94839-701 Rev - Oct 20, 2003
C-LSA02-631/D Issue 1 Jul 19, 2002	-	-	Raytheon (Beech) 99, 99A (C-FQCN / U-126, N918BB / U-118)	Radio Altimeter Antennas Installation	None	None
C-LSA01-652/D Issue 1 Sep 14, 2001	-	-	DHC-6-300 (D-GJDE / 471)	Installation of Universal CVR-30B Cockpit Voice Recorder	None	None
C-LSA01-646/D Issue 1 Sep 21, 2001	-	-	DHC-6-300 (C-GBEB / 272)	Installation of Universal CVR-30B Cockpit Voice Recorder	None	None
C-LSA01-645/D Issue 1 Aug 14, 2001	-	-	DHC-6-300 (C-GBEB / 272)	Elevator Trailing Edge Replacement	None	None
C-LSA01-636/D Issue 1 Aug 8, 2001	-	-	DHC-6-300 (C-GHBP / 380)	Fastener Replacement on the R/H Wing Spar	None	None
C-LSA01-630/D Issue 1 Jun 29, 2001	-	-	Pilatus PC-6/B-H2 (C-GAAP / 569)	Installation of Wipaire Model 6100 Seaplane Floats	Approved Manual Supplement of the Pilatus PC-6/ B2-H4 at a Gross Weight of 6100 Pounds with Wipline Model 6100 Floats Jul 14, 1994	None



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APPROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
C-LSA01-610/D Issue 1 Apr 30, 2001	-	-	Pilatus PC-6/B-H2 (C-GAAP / 569)	Gross Weight Increase	1072-20 Rev 3 May 1992	01975
C-LSA00-233/D Issue 2 Dec 5, 2000	-	-	Beechcraft Kingair 100 (C-GXVX / B18)	Installation of Dual Garmin GNS 430 NAV / COMM / GPS (IFR GPS Enroute, Terminal, Approach)	C73590 Rev N/C	None
C-LSA00-207/D Issue 1 Jun 29, 2000	-	-	Neech 100 (C-GXVX / B18)	Installation of GA-56 GPS Antennas, FS 153.3, FS 170.7 (Structural Provisions Only)	None	None
C-LSA00-174/D Issue 1 May 15, 2000	-	-	DHC-6-300 (C-FWUL / 360)	Removal Of Auxiliary Battery	None	None
C-LSA99-617/D Issue 1 Apr 27, 1999	-	-	DHC-6-300 (C-GCGW)	Ferry Fuel System		
C-LSA94-246 Issue 2 Dec 20, 1994	-	-	DHC-6-200 (V3-HTA / 112)	Installation of Pratt & Whitney PT6A-27 ENGINES	A61290 Rev A Dec 20, 1994	None
C-LSA93-130/D Issue 1 Sep 30, 1993	-	-	DHC-6-100 (C-FAWC / 108)	Baggage Door Installation	None	None
C-LSA93-041/D Issue 1 Mar 24, 1993	-	-	DHC-6-200, -210 (GKNR / 186, FJCL / 151)	CVR Installation (Structures)	None	None
W-LSA98-124/D Issue 1 Dec 20, 1998	-	-	Beechcraft Model 99 (C-FVCE / U-118, C-GAWW / U-137, C-GAVV / U-142)	Installation of PHOENIX VR-1010-24-2B Voltage Regulators	None	None
W-LSA98-123/D Issue Dec 20, 1998	-	-	Beechcraft Model 99 (C-FQCN / U-126, C-FOZU / U-130)	Installation of PHOENIX VR-1010-24-2B Voltage Regulators	None	None
W-LSA98-028/D Issue 1 Apr 20, 1998	-	-	Beech B100 (C-FQOV)	Landing Gear Retraction Motor/ Transmission Support Brackets Modification		
W-LSA97-150/D Issue 1 Feb 1, 1998	-	-	DHC-6-300 (C-GBEB / 272)	Ferry Fuel System	FMS986301 Rev 1 Jan 29, 1998	None
W-LSA97-144/D Issue 1 Dec 12, 1997	-	-	Beech 99A (C-GAWW / U-137, C-GAVV / U-142, C-GAVU / U-143)	Aft Avionics Rack Installation	None	None
W-LSA97-130/D Issue 1 Dec 4, 1997	-	-	Beech 99A (C-GAWW / U-137, C-GAVV / U-142, C-GAVU / U-143)	Radio Altimeter Antennas Installation	None	None
W-LSA97-108/D Issue 1 May 9, 1997	-	-	DHC-6-300 (C-GQKZ / 532)	Twin Otter CVR Installation	None	None
W-LSA97-026/D Issue 1 Mar 17, 1997	-	-	DHC-6-300 (C-GBGC / 701)	Replacement Fuselage Skin Panel	None	None
W-LSA95-079 Issue 1 Sep 21, 1995	-	-	DHC-6-300 (C-FMOL / 303)	Installation of a Garmin GPS 165 Global Positioning System	None	None
C-LSA95-241 Issue 2 Jun 6, 1996	-	-	DHC-6-200 (N10EA / 199, N30EA / 198)	Installation of Pratt & Whitney PT6A-27 ENGINES	None	None
W-LSA93-133 Issue 1 Dec 17, 1993	-	-	Beechcraft King Air 100 (C-FQOV / B-38)	Installation of a Trimble TNL-2000T GPS Receiver and ETS 802100-29 CDI	Dec 17, 1993	None
W-LSA92-129 Issue 1 Aug 10, 1992	-	-	DHC-6-300 (C-FMYV / 374)	Avionics installation including Radio Master, Directional Gyro, and Audio Panel	22272-801 Rev - Aug 10, 1992	None
W-LSA92-108 Issue 1 Jun 12, 1992	-	-	DHC-6 (C-FISO / 204)	Installation of HF and Compass System	None	None



129 MacLaurin Drive
Springbank Airport
Calgary, Alberta, Canada

TC APPROVAL	FAA APPROVAL	EASA APPROVAL	AIRCRAFT TYPE	DESCRIPTION	AFM	ICA
W-LSA92-06 Issue 2 Jan 17, 1992	-	-	DHC-6-300 (C-FKKV / 371)	King KT7A Transponder and ACK-A30 Encoder	None	None
W-LSA91-95 Issue 1 Jul 19, 1991	-	-	DHC-6-300 (C-FIZD / 461)	Avionics Refit	None	None
W-LSA91-076 Issue 1 Aug 7, 1991	-	-	Piper PA28 140 (C-GIHE / 28-7225443)	Blind Altitude Encoder Installation	None	None
W-LSA91-073 Issue 1 Aug 6, 1991	-	-	Cessna A185E (C-FTTJ / 185E-1085)	Blind Altitude Encoder Installation	None	None
W-LSA91-072 Issue 1 Jun 5, 1991	-	-	Cessna U206B (C-FVSJ / U206B-0819)	ACK A30 Encoder Installation	None	None
W-LSA91-071 Issue 1 Jun 7, 1991	-	-	Piper PA-24 (C-FMEB / 242094)	Installation of ACK A30 Blind Altitude Encoder and AT50A Transponder	None	None