



ROCKY MOUNTAIN AIRCRAFT

Complete Aircraft Support - Sales - Leasing - Maintenance - Parts - Avionics

129 MacLaurin Drive, Springbank Airport, Calgary, Alberta T3Z 3S4

Tel: 403-288-3305 Fax: 403-247-6846

www.rockymountainaircraft.ca

6th October 2020

Blanket Authorization

To whom it may concern,

The purchase of parts to be installed under the following STCs confers upon the purchaser the right to use the STC for the installation of those parts with no need to seek further approval

Transport Canada STC

FAA STC

EASA STC

SA02-1

SA02387NY

10072230

Installation, Substitute Passenger Cabin and Cargo Baggage Floor Panels

SA16-45

SA03757NY

10071669

Installation of Replacement Fuel Manifold Tubes

SA20-44


10074217

Installation, Replacement Cabin Roof Escape Hatch

A list the relevant parts follows

STC#	OEM Part Number	Replacement Number/s
SA02-1/SA02387NY/10072230	C6FS3474-1	RMA-C6FS3474-1 C92101-3/23
	C6FS3474-11	RMA-C6FS3474-11 C92101-17/37
	C6FS3474-13	RMA-C6FS3474-13 C92101-9/29
	C6FS3474-15	RMA-C6FS3474-15 C92101-19/39
	C6FS3474-17	RMA-C6FS3474-17 C92101-7/27
	C6FS3474-3	RMA-C6FS3474-3 C92101-5/25
	C6FS3474-5	RMA-C6FS3474-5 C92101-11/31
	C6FS3474-6	RMA-C6FS3474-6 C92101-6/26
	C6FS3474-7	RMA-C6FS3474-7 C92101-13/33
	C6FS3474-8	RMA-C6FS3474-8 C92101-8/28
	C6FS3474-9	RMA-C6FS3474-9 C92101-15/35
	C6FS2794-1	RMA-C6FS2794-1 E324100-3
	C6FS2794-3	RMA-C6FS2794-3 E324100-5
	SA16/45/SA03757NY/10071669	C6PF1127-27
C6PF1127-29		RMA-C6PF1052-5 RMA-C6PF1127-29
C6PF1127-31		RMA-C6PF1052-9 RMA-C6PF1127-31
C6PF1127-33		RMA-C6PF1052-11 RMA-C6PF1127-33
C6PF1127-35		RMA-C6PF1052-13 RMA-C6PF1127-35
C6PF1127-37		RMA-C6PF1052-15 RMA-C6PF1127-37
SA20-44/10074217	C6FS2413-11	RMA-C6FS2413-11

Regards



Mel Cornelius

Director of Maintenance/Person Responsible for Maintenance

Rocky Mountain Aircraft