

FUEL CELL SUMP PLATE ASSEMBLIES FOR DHC-6 FUEL SYSTEM

A COMPLETE SOLUTION

We have another compliment to your DHC-6 Fuel Gallery. The Fuel Cell Sump Plate Assemblies built under our exclusively held Transport Canada PDA18-10 are a direct replacement for the OEM parts on all series of De Havilland Twin Otter.

Whether your operation utilizes standard-style fuel boost pumps, or canister-type (S.O.O. 6159), we have the solution to fit your need.



**GIVE YOUR TWIN
OTTER A RENEWED
FUEL SYSTEM
WITH THE ROBUST,
HIGH-CALIBRE PARTS
IT DESERVES**

EFFECTIVE PDA REPLACEMENT

These manufactured parts are a quality replacement item that interfaces with both the OEM and Rocky Mountain Aircraft's replacement Fuel Manifold Tubes (STC SA16-45), and Tees and Elbow(s) (PDA21-11).

OEM PART NUMBER

C6PF1016-15
C6PF1016-19
C6PF1016-21
C6PF1016-25
C6PF1048-3
C6PF1104-3
C6PF1161-1

RMA PDA PART NUMBER

RMA-C6PF1016-15
RMA-C6PF1016-19
RMA-C6PF1016-21
RMA-C6PF1016-25
RMA-C6PF1048-3
RMA-C6PF1104-3
RMA-C6PF1161-1

FUEL CELL NUMBER

2 AND 3
7
1
8
6
4 AND 5
4 AND 5 (S.O.O. 6159)

CONTACT US

129 MACLAURIN DRIVE | CALGARY, ALBERTA, T3Z 3S4 | PHONE 403-288-3305 | TOLL FREE 1-800-661-1130
INFO@ROCKYMOUNTAINAIRCRAFT.CA



ROCKY MOUNTAIN AIRCRAFT